

ISO 15011-2:2009-10 (E)

Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 2: Determination of the emission rates of carbon monoxide (CO), carbon dioxide (CO₂), nitrogen monoxide (NO) and nitrogen dioxide (NO₂) during arc welding, cutting and gouging

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Equipment and materials	2
6	Test procedures	4
6.1	Welding procedure selection	4
6.2	Setting up the test equipment	4
6.3	Blank test	5
6.4	Manual metal arc welding	5
6.5	Continuous wire processes and autogeneous TIG welding	5
6.6	Cutting and gouging	6
7	Calculating and reporting the results	7
Annex A (informative)	Possible designs of hood	8
Annex B (informative)	Equipment notes	10
Annex C (informative)	Welding parameters for gas-shielded arc welding	12
Annex D (normative)	Test procedures	15
Annex E (normative)	Calculation of the average stable gas concentration	16
Annex F (normative)	Test report	17
Bibliography		18