

# ISO 15011-1:2009-10 (E)

## Health and safety in welding and allied processes - Laboratory method for sampling fume and gases - Part 1: Determination of fume emission rate during arc welding and collection of fume for analysis

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 Scope .....		1
2 Normative references .....		1
3 Terms and definitions .....		1
4 Principle .....		2
5 Equipment and materials .....		2
6 Tests procedures .....		3
6.1 Welding procedure selection .....		3
6.2 Manual metal arc welding .....		3
6.3 Continuous wire processes .....		5
6.4 Analysis of the fume collected .....		7
7 Calculating and reporting the results .....		7
Annex A (informative) Possible designs of test chamber .....		8
Annex B (informative) Equipment notes .....		14
Annex C (informative) Welding parameters .....		16
Annex D (normative) Test procedures .....		18
Annex E (normative) Test report .....		19
Bibliography .....		20