

DIN EN 13100-4:2013-01 (E)

Non destructive testing of welded joints of thermoplastics semifinished products - Part 4: High voltage testing

Contents		Page
Foreword		3
1	Scope	4
2	Terms and definitions	4
3	Symbols and designations	4
4	Principle of the test	4
5	Equipment types	5
5.1	General	5
5.2	High frequency spark tester	5
5.3	DC Holiday detector	5
5.4	Pulsed Holiday detector	6
6	Determination of test voltage	6
6.1	General	6
6.2	Butt joints	6
6.3	Overlap joints	7
7	Test electrode	8
8	Test procedure	8
8.1	DC and pulsed holiday detectors	8
8.2	High frequency spark testers	9
9	Test report	9