

DIN EN ISO 15618-1:2016-12 (E)

Qualification testing of welders for underwater welding - Part 1: Hyperbaric wet welding (ISO 15618-1:2016)

Contents		Page
European foreword		3
Foreword		4
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	7
4	Symbols and abbreviations	7
4.1	General	7
4.2	Test piece	7
4.3	Filler materials and fluxes	8
4.4	Miscellaneous	8
5	Essential variables for qualification testing	8
5.1	General	8
5.2	Welding processes	8
5.3	Joint types (butt and fillet welds)	9
5.4	Material groups	9
5.5	Filler materials and fluxes	9
5.6	Dimensions	9
5.7	Welding positions	10
5.8	Hyperbaric environment	10
5.9	Visibility	10
6	Range of qualification	10
6.1	General	10
6.2	Welding process	10
6.3	Joint types	11
6.4	Material groups	11
6.5	Filler materials	12
6.6	Dimensions	12
6.7	Welding positions	12
6.8	Hyperbaric environment	12
7	Examination and testing	14
7.1	General	14
7.2	Witnessing	14
7.3	Shapes and dimensions of test pieces	14
7.4	Welder-diver qualification test criteria	16
7.5	Test methods	16
7.6	Test pieces and test specimens	17
7.6.1	General	17
7.6.2	Butt welds in plate and pipe	17
7.6.3	Fillet welds on plate and pipe	18
7.7	Test report	20
8	Acceptance requirements for test pieces	20
9	Re-tests	20
10	Period and confirmation of validity	20
11	Revalidation of welder-diver qualification	21
12	Welder-diver qualification test certificate	21
13	Designation	21

Annex A (informative) Welder-diver qualification test certificate for hyperbaric wet welding	23
Annex B (informative) Job knowledge	25
Bibliography	27