

ISO 21904-3:2018-02 (E)

Health and safety in welding and allied processes - Requirements, testing and marking of equipment for air filtration - Part 3: Determination of the capture efficiency of on-torch welding fume extraction devices

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	2
5	Test equipment and materials	2
5.1	General requirement	2
5.2	Test equipment	2
6	Test procedure	4
6.1	Preliminary tests	4
6.1.1	Setting the shielding gas flow rate	4
6.1.2	Measuring the flow rates and determination of leakage	4
6.1.3	Establishing the arcing time for total fume emission rate test	5
6.1.4	Setting up the test equipment	5
6.2	Capture efficiency tests	6
6.2.1	General	6
6.2.2	Test procedure	6
6.2.3	Calculation of the results	7
7	Test parameters for generating capture efficiency data	8
8	Test report	9
Annex A (informative) Equipment notes		10
Annex B (normative) Trial tests		12
Annex C (informative) Examples of test chambers		14
Annex D (normative) Test procedures		16
Annex E (informative) Data processing for test method 3		17
Annex F (normative) Test parameters form to be filled		19
Annex G (informative) Information about the necessity to measure leakage		20
Bibliography		21