

# ISO 14744-5:2000-04 (E)

## Welding — Acceptance inspection of electron beam welding machines — Part 5: Measurement of run - out accuracy

---

### Contents

	Page
Foreword .....	v
<b>1 Scope</b> .....	<b>1</b>
<b>2 Normative reference</b> .....	<b>1</b>
<b>3 Termes et définitions</b> .....	<b>1</b>
<b>4 Test arrangement and procedures</b> .....	<b>2</b>
4.1 General .....	2
4.2 Scope of measurement .....	2
4.3 Instruments and instructions for their use .....	2
<b>5 Evaluation of measurements</b> .....	<b>2</b>