

ISO 9455-17:2024-01 (E)

Soft soldering fluxes - Test methods - Part 17: Surface insulation resistance comb test and electrochemical migration test of flux residues

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	1
5	Reagents	2
6	Apparatus	2
7	Inspection of test coupons	8
7.1	Surface plating	8
7.1.1	Slivering (thin metal overhang on etch runs)	8
7.1.2	Plating nodules	9
7.1.3	Plating pits	9
7.2	Surface laminate	9
8	Sample preparation	9
8.1	Preparation of the flux test solution	9
8.1.1	Liquid flux samples	9
8.1.2	Solid flux samples	9
8.1.3	Flux-cored solder wire or preform samples	9
8.1.4	Solder paste samples	10
8.1.5	Paste flux samples	10
8.2	Preparation of the test coupons	10
8.2.1	Sample identification	10
8.2.2	Test coupons	10
8.2.3	Test coupon pre-cleaning	11
9	Procedure	11
9.1	Methods for connecting test coupons	11
9.1.1	Board circuitry layout	11
9.1.2	Preconditioning of SIR test coupons prior to processing (optional)	13
9.2	Fluxing and soldering test patterns	13
9.2.1	Liquid and solid flux samples and flux-cored solder wire samples	13
9.2.2	Soldering using wave solder system	13
9.2.3	Soldering using static solder pot	13
9.2.4	Solder paste samples	14
9.2.5	Paste flux samples	14
9.3	Cleaning	14
9.4	SIR measurement	15
9.4.1	High-resistance measurement system verification	15
9.4.2	Test coupon measurements	15
9.5	Electrochemical migration test	15
10	Assessment	16

11	Precision	16
12	Test report	16
	Annex A (informative) SIR testing guidance	18
	Annex B (informative) Surface insulation resistance comb test and electrochemical migration test of flux residues -- Qualification test report	20
	Bibliography	22