

ISO 10882-2:2024-04 (E)

Health and safety in welding and allied processes - Sampling of airborne particles and gases in the operator's breathing zone - Part 2: Sampling of gases

Contents		Page
Foreword		v
Introduction		vi
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
3.1	General terms	2
3.2	Measurement terms	2
3.3	Welding terms	4
3.4	Analytical terms	4
4	Description of measurement methods	5
4.1	General	5
4.2	Direct reading electrical apparatus	6
4.2.1	Applicability	6
4.2.2	Operating principles	6
4.2.3	Availability	6
4.3	Detector tubes	6
4.3.1	Applicability	6
4.3.2	Pumped detector tubes	6
4.3.3	Diffusive detector tubes	7
4.4	Indirect methods involving laboratory analysis	7
4.4.1	Applicability	7
4.4.2	Pumped sampler methods	7
4.4.3	Diffusive sampler methods	8
5	Requirements	8
6	Assessment strategy	8
7	Measurement strategy	9
7.1	General	9
7.2	Personal exposure measurements	9
7.3	Fixed-point measurements	9
7.4	Selection of measurement conditions and measurement pattern	9
7.4.1	General	9
7.4.2	Screening measurements of time-weighted average concentration and worst- case measurements	9
7.4.3	Measurements for comparison with occupational exposure limit values and periodic measurements	10
8	Sampling	10
8.1	Sampling position	10
8.1.1	Personal sampling	10
8.1.2	Fixed-point sampling	11
8.2	Sampling equipment	11
8.2.1	Direct reading electrical apparatus	11
8.2.2	Detector tubes	11

8.2.3	Pumped sorbent tubes	11
8.2.4	Diffusive samplers	11
8.2.5	Construction materials	11
8.3	Sample filtration	11
8.4	Multiple sampling	11
8.5	Volume of sampling line	12
8.6	Flow rate	12
8.7	Handling of temperature, pressure and humidity data	12
9	Measurement of individual gases and vapours	12
9.1	General	12
9.2	Ozone (0,01 ppm to 3 ppm)	12
9.2.1	Special sampling requirements	12
9.2.2	Direct reading electrical apparatus	12
9.2.3	Detector tubes	13
9.2.4	Indirect methods involving laboratory analysis	13
9.3	Carbon monoxide (3 ppm to 500 ppm)	13
9.3.1	Direct reading electrical apparatus	13
9.3.2	Detector tubes	13
9.3.3	Indirect methods involving laboratory analysis	13
9.4	Carbon dioxide (500 ppm to 100 000 ppm)	13
9.4.1	Origin	13
9.4.2	Direct reading electrical apparatus	13
9.4.3	Detector tubes	14
9.4.4	Indirect methods involving laboratory analysis	14
9.5	Nitric oxide (1 ppm to 100 ppm) and nitrogen dioxide (0,3 ppm to 250 ppm)	14
9.5.1	General	14
9.5.2	Direct reading electrical apparatus	14
9.5.3	Detector tubes	14
9.5.4	Indirect methods involving laboratory analysis	14
9.6	Vapours	15
9.6.1	General	15
9.6.2	Direct reading electrical apparatus	15
9.6.3	Detector tubes	15
9.6.4	Indirect methods involving laboratory analysis	15
10	Recording of test data and presentation of results	15
	Annex A (informative) Measurement of individual gases and vapours	17
	Annex B (informative) Example of a test report	18
	Bibliography	21