

ISO 13919-2:2001-10 (E)

Welding_ - Electron and laser beam welded joints; Guidance on quality levels for imperfections_-
Part_2: Aluminium and its weldable alloys

Contents		Page
Foreword		v
Introduction		v
1 Scope		1
2 Normative references		1
3 Symbols		2
4 Evaluation of welds		2
Annex A (informative)		10