

# ISO 15618-1:2001-12 (E)

## Qualification testing of welders for underwater welding\_ Part\_1: Diver-welders for hyperbaric wet welding

---

<b>Contents</b>		Page
<b>Foreword</b> .....		v
<b>Introduction</b> .....		1
<b>1 Scope</b> .....		1
<b>2 Normative references</b> .....		1
<b>3 Terms and definitions</b> .....		3
<b>4 Symbols and abbreviations</b> .....		3
4.1 General .....		3
4.2 Test piece .....		3
4.3 Consumable .....		3
4.4 Miscellaneous .....		3
<b>5 Essential variables for approval testing</b> .....		3
5.1 General .....		3
5.2 Welding processes .....		3
5.3 Joint types (butt and fillet welds) .....		4
5.4 Material groups .....		4
5.5 Consumables .....		4
5.6 Dimensions .....		4
5.7 Welding positions .....		5
5.8 Hyperbaric environment .....		5
<b>6 Range of approval</b> .....		5
6.1 General .....		5
6.2 Welding process .....		5
6.3 Joint types .....		5
6.4 Material groups .....		6
6.5 Consumables .....		6
6.6 Dimensions .....		6
6.7 Welding positions .....		6
6.8 Hyperbaric environment .....		7
<b>7 Examination and testing</b> .....		8
7.1 General .....		8
7.2 Supervision .....		8
7.3 Shapes and dimensions of test pieces .....		8
7.4 Welding conditions .....		13
7.5 Test methods .....		13
7.6 Test pieces and test specimens .....		14
<b>8 Acceptance requirements for test pieces</b> .....		18
<b>9 Re-tests</b> .....		19
<b>10 Period of validity</b> .....		19
10.1 Initial approval .....		19
10.2 Prolongation .....		19
<b>11 Certificate</b> .....		19
<b>12 Designation</b> .....		20
<b>Annex A</b> (informative) Diver-welder approval test certificate for hyperbaric wet welding .....		21
<b>Annex B</b> (informative) Job knowledge .....		23