

ISO 9692-4:2003-08 (E)

Welding and allied processes - Recommendations for joint preparation - Part 4: Clad steels

Contents	Page
Foreword	v
1 Scope	1
2 Normative references	1
3 Materials	1
4 Types of joint preparation	1
Table 1 -- Joint preparation for clad steels welded from both sides	2
Table 2 -- Joint preparation for clad steels welded from both sides with cladding removal	4
Table 3 -- Joint preparation for clad steels welded from one side	6
Table 4 - Joint preparation for clad steels incorporating a backing, insert or cover strip	8
Bibliography	10