

# ISO 15614-10:2005-02 (E)

## Specification and qualification of welding procedures for metallic materials - Welding procedure test - Part 10: Hyperbaric dry welding

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Preliminary welding procedure specification (pWPS) .....	2
5	Welding procedure test .....	3
6	Test piece .....	3
6.1	General .....	3
6.2	Shape and dimensions of test pieces .....	3
6.3	Welding of test pieces .....	3
7	Examination and testing .....	4
7.1	Extent of testing .....	4
7.2	Location and cutting of test specimens .....	4
7.3	Non-destructive testing .....	4
7.4	Destructive tests .....	4
7.5	Re-testing .....	4
8	Range of qualification .....	4
8.1	General .....	4
8.2	Related to the manufacturer .....	5
8.3	Related to the parent material .....	5
8.4	Common to all welding procedures .....	5
8.5	Specific to processes .....	7
8.6	Specific to hyperbaric environment .....	7
9	Welding procedure qualification record (WPQR) .....	8