

# ISO 10042:2005-11 (E)

## Welding - Arc-welded joints in aluminium and its alloys - Quality levels for imperfections

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>Introduction</b> .....		<b>v</b>
<b>1 Scope</b> .....		<b>1</b>
<b>2 Normative references</b> .....		<b>1</b>
<b>3 Terms and definitions</b> .....		<b>2</b>
<b>4 Symbols</b> .....		<b>3</b>
<b>5 Assessment of imperfections</b> .....		<b>3</b>
<b>Annex A (informative) Examples of the determination of the percent porosity</b> .....		<b>16</b>
<b>Annex B (informative) Additional information and guidelines for users of this International Standard</b> .....		<b>18</b>
<b>Bibliography</b> .....		<b>19</b>