

ISO 15614-6:2006-04 (E)

Specification and qualification of welding procedures for metallic materials - Welding procedure test - Part 6: Arc and gas welding of copper and its alloys

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Welding processes	2
5	Preliminary welding procedure specification (pWPS)	2
6	Welding procedure test	3
7	Test piece	3
7.1	General	3
7.2	Shape and dimensions of test pieces	3
7.3	Welding of test pieces	4
8	Examination and testing	7
8.1	Extent of testing	7
8.2	Location and taking of test specimens	8
8.3	Non-destructive testing	8
8.4	Destructive testing	12
8.5	Acceptance levels	13
8.6	Re-testing	13
9	Range of qualification	14
9.1	General	14
9.2	Related to the manufacturer	14
9.3	Related to the parent material	14
9.4	Common to all welding procedures	16
9.5	Specific to processes	18
10	Welding procedure qualification record (WPQR)	18
Annex A (informative)	Welding Procedure Qualification Record form (WPQR)	19
Bibliography		22