

# DIN EN ISO 5817:2006-10 (E)

**Welding - Fusion-welded joints in steel, nickel, titanium and their alloys (beam welding excluded) - Quality levels for imperfections (ISO 5817:2003 + Cor. 1:2006)**

---

| <b>Contents</b>  | <b>Page</b> |
|--|-------------|
| <b>Foreword</b> .....  | <b>3</b>    |
| <b>Introduction</b> .....  | <b>4</b>    |
| <b>1 Scope</b> .....   | <b>5</b>    |
| <b>2 Normative references</b> .....  | <b>6</b>    |
| <b>3 Terms and definitions</b> .....   | <b>6</b>    |
| <b>4 Symbols</b> .....   | <b>7</b>    |
| <b>5 Assessment of imperfections</b> .....   | <b>8</b>    |
| <b>Annex A (informative) Examples of determination of percentage (%) porosity</b> .....  | <b>26</b>   |
| <b>Annex B (informative) Additional information and guidelines for use of this International Standard</b> .....                              | <b>28</b>   |
| <b>Annex ZA (informative) Clauses of this European Standard addressing essential requirements or other provisions of EU directives</b> ..... | <b>29</b>   |
| <b>Annex ZB (normative) Normative references to international publications with their relevant European publications</b> .....               | <b>30</b>   |
| <b>Bibliography</b> .....  | <b>31</b>   |