

DIN EN ISO 15614-6:2007-01 (E)

**Specification and qualification of welding procedures for metallic materials -
Welding procedure test - Part 6: Arc and gas welding of copper and its alloys (ISO
15614-6:2006)**

Contents

	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	6
4 Welding processes	6
5 Preliminary welding procedure specification (pWPS)	6
6 Welding procedure test	7
7 Test piece	7
7.1 General	7
7.2 Shape and dimensions of test pieces	7
7.3 Welding of test pieces	8
8 Examination and testing	11
8.1 Extent of testing	11
8.2 Location and taking of test specimens	12
8.3 Non-destructive testing	12
8.4 Destructive testing	16
8.5 Acceptance levels	17
8.6 Re-testing	17
9 Range of qualification	18
9.1 General	18
9.2 Related to the manufacturer	18
9.3 Related to the parent material	18
9.4 Common to all welding procedures	20
9.5 Specific to processes	22
10 Welding procedure qualification record (WPQR)	22
Annex A (informative) Welding Procedure Qualification Record form (WPQR)	23
Annex ZA (informative) Relationship between this International Standard and the Essential Requirements of EU Directive 97/05/IEC	26
Bibliography	27