

# DIN EN 482:2012-06 (E)

## Workplace exposure - General requirements for the performance of procedures for the measurement of chemical agents

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
<b>1</b>	<b>Scope .....</b>	<b>5</b>
<b>2</b>	<b>Normative references .....</b>	<b>5</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>6</b>
<b>4</b>	<b>Classification .....</b>	<b>6</b>
4.1	General .....	6
4.2	Screening measurements of time weighted average concentration .....	6
4.3	Screening measurements of variation of concentration in time and/or space .....	6
4.4	Measurements for comparison with (occupational exposure) limit values and periodic measurements .....	6
<b>5</b>	<b>Performance requirements .....</b>	<b>6</b>
5.1	General .....	6
5.2	Screening measurements of time weighted average concentration .....	7
5.3	Screening measurements of variation of concentration in time and/or space .....	7
5.4	Measurements for comparison with limit values and periodic measurements .....	7
5.4.1	Unambiguity .....	7
5.4.2	Selectivity .....	7
5.4.3	Averaging time .....	7
5.4.4	Measuring range .....	7
5.4.5	Expanded uncertainty .....	8
5.5	Composite procedures .....	8
5.6	Transport and storage .....	8
5.7	Environmental conditions .....	8
5.8	Description of measuring procedure .....	9
5.9	Dimension of result .....	9
5.10	Additional requirements .....	9
<b>6</b>	<b>Test method .....</b>	<b>9</b>
<b>7</b>	<b>Validation report .....</b>	<b>10</b>
<b>Annex A (informative) Structure of a method description .....</b>		<b>11</b>
<b>Annex B (informative) Calculation of uncertainty of measurement .....</b>		<b>12</b>
B.1	General .....	12
B.2	Uncertainty associated with sampled air volume or mass uptake .....	13
B.3	Uncertainty associated with sampling efficiency .....	15
B.4	Uncertainty associated with sample storage and transportation .....	17
B.5	Uncertainty associated with method recovery for gases and vapours .....	17
B.6	Uncertainty associated with analytical recovery for airborne particles and mixtures of airborne particles and vapour .....	17
B.7	Uncertainty associated with method variability for gases and vapours .....	18

<b>B.8</b>	<b>Uncertainty associated with analytical variability for airborne particles and mixtures of airborne particles and vapour .....</b>	<b>18</b>
<b>B.9</b>	<b>General equation for combination of uncertainty components .....</b>	<b>18</b>
	<b>Bibliography .....</b>	<b>20</b>