

ISO 15202-2:2012-02 (E)

Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 2: Sample preparation

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	2
3	Terms and definitions	2
4	Principle	4
5	Requirements	4
6	Reactions	4
7	Reagents	5
8	Laboratory apparatus	5
9	Procedure	6
9.1	Soluble metal and metalloid compounds	6
9.2	Total metals and metalloids and their compounds	6
9.3	Mixed exposure	6
10	Special cases	7
10.1	Action to be taken if there is doubt about the effectiveness of the selected sample dissolution method	7
10.2	Action to be taken when particles have become dislodged from the filter during transportation	7
10.3	Action to be taken regarding sampler wall deposits	7
11	Laboratory records	7
Annex A (informative)	Safety precautions to be observed when using hydrofluoric and perchloric acids ...	8
Annex B (normative)	Sample dissolution method for soluble metal and metalloid compounds	9
Annex C (normative)	Sample dissolution using nitric acid and hydrochloric acid on a hotplate	15
Annex D (normative)	Sample dissolution using hydrofluoric and nitric acids and ultrasonic agitation .	19
Annex E (normative)	Sample dissolution using sulfuric acid and hydrogen peroxide on a hotplate	22
Annex F (normative)	Sample dissolution using nitric acid and perchloric acid on a hotplate	26
Annex G (normative)	Sample dissolution in a closed vessel microwave dissolution system	30
Annex H (normative)	Sample dissolution at 95 °C using a hot block	35

Annex I (normative) Action to be taken when there is visible, undissolved, particulate material after sample dissolution	38
Annex J (informative) Sampler wall deposits	43
Bibliography	45