

# ISO 17733:2015-12 (E)

## Workplace air - Determination of mercury and inorganic mercury compounds - Method by cold- vapour atomic absorption spectrometry or atomic fluorescence spectrometry

---

<b>Contents</b>		<b>Page</b>
Foreword .....		vi
Introduction .....		vii
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>2</b>
<b>3.1</b>	<b>General definitions .....</b>	<b>2</b>
<b>3.2</b>	<b>Particle size fraction definitions .....</b>	<b>3</b>
<b>3.3</b>	<b>Sampling definitions .....</b>	<b>3</b>
<b>3.4</b>	<b>Analytical definitions .....</b>	<b>4</b>
<b>3.5</b>	<b>Statistical terms .....</b>	<b>6</b>
<b>4</b>	<b>Principle .....</b>	<b>7</b>
<b>5</b>	<b>Interferences .....</b>	<b>7</b>
<b>6</b>	<b>Requirement .....</b>	<b>8</b>
<b>7</b>	<b>Reagents .....</b>	<b>8</b>
<b>8</b>	<b>Apparatus .....</b>	<b>10</b>
<b>8.1</b>	<b>Sampling equipment for diffusive sampling .....</b>	<b>10</b>
<b>8.2</b>	<b>Sampling equipment for pumped sampling .....</b>	<b>11</b>
<b>8.3</b>	<b>Laboratory apparatus .....</b>	<b>14</b>
<b>8.4</b>	<b>Analytical instrumentation .....</b>	<b>16</b>
<b>9</b>	<b>Occupational exposure assessment .....</b>	<b>21</b>
<b>9.1</b>	<b>General .....</b>	<b>21</b>
<b>9.2</b>	<b>Personal sampling .....</b>	<b>21</b>
<b>9.3</b>	<b>Static (area) sampling .....</b>	<b>21</b>
<b>9.4</b>	<b>Selection of measurement conditions and measurement pattern .....</b>	<b>22</b>
<b>9.4.1</b>	<b>General .....</b>	<b>22</b>
<b>9.4.2</b>	<b>Screening measurements of variation of concentration in time and/or space .....</b>	<b>22</b>
<b>9.4.3</b>	<b>Screening measurements of time-weighted average concentration and worst case measurements .....</b>	<b>22</b>
<b>9.4.4</b>	<b>Measurements near an emission source .....</b>	<b>22</b>
<b>9.4.5</b>	<b>Measurements for comparison with limit values and periodic measurements .....</b>	<b>22</b>
<b>10</b>	<b>Sampling .....</b>	<b>23</b>
<b>10.1</b>	<b>Selection of sampling method .....</b>	<b>23</b>
<b>10.1.1</b>	<b>Measurement of mercury vapour .....</b>	<b>23</b>
<b>10.1.2</b>	<b>Measurement of particulate inorganic mercury compounds .....</b>	<b>23</b>
<b>10.1.3</b>	<b>Measurement of mercury vapour and particulate inorganic mercury compounds .....</b>	<b>23</b>
<b>10.2</b>	<b>Consideration of temperature and pressure effects .....</b>	<b>24</b>
<b>10.2.1</b>	<b>Effect of temperature and pressure on the uptake rate of diffusive badges .....</b>	<b>24</b>

10.2.2	Effect of temperature and pressure on volumetric flow rate in the pumped sampling method .....	24
10.2.3	Expression of results .....	24
10.3	Diffusive sampling .....	24
10.3.1	Selection and use of diffusive badges .....	24
10.3.2	Preparation for sampling .....	25
10.3.3	Sampling position .....	26
10.3.4	Sample collection .....	26
10.3.5	Transportation of samples .....	26
10.4	Pumped sampling .....	27
10.4.1	Preliminary considerations .....	27
10.4.2	Preparation for sampling .....	28
10.4.3	Sampling position .....	29
10.4.4	Collection of samples .....	30
10.4.5	Transportation of samples .....	30
11	Analysis .....	31
11.1	General .....	31
11.2	Cleaning of glassware and plasticware .....	31
11.3	Preparation of blank, sample and calibration solutions for analysis of diffusive badges ..	31
11.3.1	Preparation of blank and sample solutions .....	31
11.3.2	Preparation of calibration solutions .....	32
11.4	Preparation of blank, sample and calibration solutions for analysis of pumped samples.33	
11.4.1	Preparation of blank and sample solutions .....	33
11.4.2	Preparation of calibration solutions .....	34
11.5	Instrumental analysis .....	35
11.5.1	Setting up the instrument .....	35
11.5.2	Introduction of solutions into the mercury cold-vapour generation system .....	36
11.5.3	Conditioning the mercury cold-vapour generation system .....	36
11.5.4	Check for contamination of the reagents and/or system .....	37
11.5.5	Calibration .....	37
11.5.6	Determination .....	38
11.6	Estimation of detection and quantification limits .....	39
11.6.1	Estimation of the instrumental detection limit .....	39
11.6.2	Estimation of the method detection limit and the quantification limit .....	39
11.7	Quality control .....	40
11.7.1	Reagent blanks and laboratory blanks .....	40
11.7.2	Quality control solutions .....	40
11.7.3	Certified reference materials (CRMs) .....	40
11.7.4	External quality assessment .....	40
11.8	Measurement uncertainty .....	40
12	Expression of results .....	41
12.1	Calculation of the volume of air samples .....	41
12.1.1	Diffusive sampling .....	41
12.1.2	Pumped sampling .....	41
12.2	Calculation of mercury in air concentrations .....	41
13	Method performance .....	42
13.1	General .....	42
13.2	Detection and quantification limits .....	42
13.2.1	Sampling with diffusive badges and analysis by cold-vapour atomic absorption spectrometry .....	42
13.2.2	Sampling with pumped sorbent tubes and analysis by cold-vapour atomic absorption spectrometry .....	42
13.2.3	Sampling with pumped sorbent tubes and analysis by cold-vapour atomic fluorescence spectrometry .....	42
13.2.4	Sampling with inhalable samplers and analysis by cold-vapour atomic absorption spectrometry .....	42
13.3	Upper limits of the analytical range .....	43
13.4	Blank values .....	43

<b>13.5</b>	<b>Bias and precision .....</b>	<b>43</b>
<b>13.5.1</b>	<b>Analytical bias .....</b>	<b>43</b>
<b>13.5.2</b>	<b>Analytical precision .....</b>	<b>43</b>
<b>13.5.3</b>	<b>Overall bias of sampling and analysis methods .....</b>	<b>44</b>
<b>13.5.4</b>	<b>Overall precision of sampling and analysis methods .....</b>	<b>44</b>
<b>13.6</b>	<b>Overall uncertainty of sampling and analysis methods .....</b>	<b>44</b>
<b>13.7</b>	<b>Effects on sampler performance .....</b>	<b>45</b>
<b>13.7.1</b>	<b>Effect of exposure concentration and time on sampler performance .....</b>	<b>45</b>
<b>13.7.2</b>	<b>Effect of atmospheric temperature, pressure and humidity on sampler performance .....</b>	<b>45</b>
<b>13.7.3</b>	<b>Effect of air velocity on performance of diffusive badges .....</b>	<b>45</b>
<b>13.8</b>	<b>Sample uptake rate and sampling capacity of diffusive badges .....</b>	<b>46</b>
<b>13.9</b>	<b>Collection efficiency, breakthrough volume and sampling capacity of sorbent tubes .....</b>	<b>46</b>
<b>13.10</b>	<b>Storage stability .....</b>	<b>46</b>
<b>13.11</b>	<b>Mechanical strength .....</b>	<b>46</b>
<b>13.12</b>	<b>Interferences .....</b>	<b>46</b>
<b>14</b>	<b>Test report .....</b>	<b>47</b>
<b>14.1</b>	<b>Test record .....</b>	<b>47</b>
<b>14.2</b>	<b>Laboratory report .....</b>	<b>48</b>
	<b>Annex A (informative) Guidance on selection of a sampling method for mercury vapour .....</b>	<b>49</b>
	<b>Annex B (informative) Temperature and pressure corrections .....</b>	<b>50</b>
	<b>Bibliography .....</b>	<b>52</b>