

ISO 20581:2016-11 (E)

Workplace air - General requirements for the performance of procedures for the measurement of chemical agents

Contents	Page
Foreword	iv
Introduction	v
1 Scope	1
2 Normative references	1
3 Terms and definitions	2
4 Classification	2
4.1 General	2
4.2 Screening measurements of time-weighted average concentration	2
4.3 Screening measurements of variation of concentration in time and/or space	2
4.4 Measurements for comparison with occupational exposure limit values	2
4.5 Periodic measurements	2
5 Performance requirements	3
5.1 General	3
5.2 Screening measurements of time-weighted average concentration	3
5.3 Screening measurements of variation of concentration in time and/or space	3
5.4 Measurements for comparison with limit values and periodic measurements	3
5.4.1 Unambiguity	3
5.4.2 Selectivity	3
5.4.3 Averaging time	4
5.4.4 Measuring range	4
5.4.5 Expanded uncertainty	4
5.4.6 Chemical agents where compliant methods are not available	4
5.5 Composite procedures	4
5.6 Transport, handling and/or storage	5
5.7 Environmental conditions	5
5.8 Description of measuring procedure	5
5.9 Dimension of result	5
5.10 Additional requirements	5
6 Test method	6
7 Validation report	7
Annex A (informative) Structure of a method description	8
Annex B (informative) Calculation of uncertainty of measurement	9
Bibliography	16