

ISO 20581:2016-11 (E)

Workplace air - General requirements for the performance of procedures for the measurement of chemical agents

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Classification	2
4.1	General	2
4.2	Screening measurements of time-weighted average concentration	2
4.3	Screening measurements of variation of concentration in time and/or space	2
4.4	Measurements for comparison with occupational exposure limit values	2
4.5	Periodic measurements	2
5	Performance requirements	3
5.1	General	3
5.2	Screening measurements of time-weighted average concentration	3
5.3	Screening measurements of variation of concentration in time and/or space	3
5.4	Measurements for comparison with limit values and periodic measurements	3
5.4.1	Unambiguity	3
5.4.2	Selectivity	3
5.4.3	Averaging time	4
5.4.4	Measuring range	4
5.4.5	Expanded uncertainty	4
5.4.6	Chemical agents where compliant methods are not available	4
5.5	Composite procedures	4
5.6	Transport, handling and/or storage	5
5.7	Environmental conditions	5
5.8	Description of measuring procedure	5
5.9	Dimension of result	5
5.10	Additional requirements	5
6	Test method	6
7	Validation report	7
Annex A (informative)	Structure of a method description	8
Annex B (informative)	Calculation of uncertainty of measurement	9
Bibliography		16