

# ISO 8518:2022-10 (E)

## Workplace air - Determination of particulate lead and lead compounds - Flame and electrothermal atomic absorption spectrometric methods

---

Contents		Page
Foreword .....		v
Introduction .....		vi
1 Scope .....		1
2 Normative references .....		1
3 Terms and definitions .....		2
4 Principle .....		2
5 Reactions .....		3
6 Requirement .....		3
7 Reagents .....		3
8 Apparatus .....		5
9 Occupational exposure assessment .....		8
9.1 Assessment strategy .....		8
9.2 Measurement strategy .....		8
9.2.1 General .....		8
9.2.2 Personal sampling .....		8
9.2.3 Static (area) sampling .....		8
9.3 Selection of measurement conditions and measurement pattern .....		8
9.3.1 General .....		8
9.3.2 Screening measurements of time-weighted average concentration and worst-case measurements .....		9
9.3.3 Screening measurements of variation of concentration in either time or space, or both .....		9
9.3.4 Measurements for comparison with limit values and periodic measurements .....		9
10 Sampling .....		9
10.1 Preliminary considerations .....		9
10.1.1 Selection and use of samplers .....		9
10.1.2 Sampling period .....		9
10.1.3 Temperature and pressure effects .....		10
10.2 Preparation of sampling equipment .....		10
10.2.1 Cleaning of samplers .....		10
10.2.2 Loading the samplers with sampling substrate .....		10
10.2.3 Setting the volumetric flow rate .....		10
10.2.4 Field blanks .....		11
10.3 Sampling position .....		11
10.3.1 Personal sampling .....		11
10.3.2 Static (area) sampling .....		11
10.4 Collection of samples .....		11
10.5 Transportation .....		12
10.6 Storage .....		12
11 Analysis .....		12

11.1	Cleaning of glassware and plasticware .....	12
11.2	Preparation of sample and blank solutions .....	13
11.2.1	General .....	13
11.2.2	Selection of sample dissolution method .....	13
11.2.3	Hot plate digestion method .....	13
11.2.4	Microwave assisted digestion method .....	13
11.2.5	Ultrasonic extraction method .....	14
11.3	Instrumental analysis .....	15
11.3.1	Selection of analytical line .....	15
11.3.2	Flame atomic absorption spectrometry .....	15
11.3.3	Electrothermal atomic absorption spectrometry .....	16
11.4	Estimation of the instrumental detection limit .....	18
11.5	Estimation of the method detection limit and method quantification limit .....	18
11.6	Quality control .....	18
11.6.1	General .....	18
11.6.2	Reagent blanks and media blanks .....	19
11.6.3	Spiked samples and spiked duplicate samples .....	19
11.6.4	Certified reference materials .....	19
11.6.5	External quality assessment .....	19
12	Expression of results .....	19
12.1	Calculation .....	19
12.2	Method performance .....	20
12.2.1	Sample collection .....	20
12.2.2	Hot plate digestion and flame atomic absorption spectrometry .....	20
12.2.3	Microwave assisted digestion and flame atomic absorption spectrometry .....	20
12.2.4	Ultrasonic extraction and flame atomic absorption spectrometry .....	20
12.2.5	Hot plate digestion and electrothermal atomic absorption spectrometry .....	20
12.2.6	Microwave assisted digestion and electrothermal atomic absorption spectrometry .....	20
12.2.7	Ultrasonic extraction and electrothermal atomic absorption spectrometry .....	21
13	Special cases .....	21
14	Test report .....	21
	<b>Annex A (informative) Guidance on filter selection .....</b>	<b>23</b>
	<b>Annex B (informative) Sampler wall deposits .....</b>	<b>26</b>
	<b>Annex C (normative) Temperature and pressure correction .....</b>	<b>28</b>
	<b>Bibliography .....</b>	<b>30</b>