

ISO 22578-2:2024-02 (E)

Graphical symbols - Safety colours and safety signs - Part 2: Measurement of photopic luminance of phosphorescent components used in a natural disaster safety way guidance system

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Test specification	1
4.1	Test specimens	1
4.2	Conditioning	2
4.3	Ambient conditions	2
4.4	Irradiance, illuminance and luminance instrumentation	2
4.4.1	Irradiance instrumentation	2
4.4.2	Illuminance instrumentation	2
4.4.3	Luminance instrumentation	3
4.5	Excitation light conditions	3
4.6	Luminance measurements	3
4.6.1	General	3
4.6.2	Telephotometer method	3
4.6.3	Contact method	3
4.6.4	Luminance recordings	4
4.7	Test report	4
4.8	Marking of phosphorescent materials	5
Bibliography		6