

# DIN EN 15051-1:2026-01 (E)

## Workplace exposure - Measurement of the dustiness of bulk materials - Part 1: Requirements and choice of test methods

---

<b>Contents</b>		<b>Page</b>
European foreword .....		3
Introduction .....		4
1	Scope .....	6
2	Normative references .....	6
3	Terms and definitions .....	6
4	Principle .....	7
5	General procedures .....	7
5.1	Schematic overview of the procedure .....	7
5.2	Conditioning of the bulk material .....	8
5.2.1	As-received condition .....	8
5.2.2	Conditioning specifications .....	9
5.3	Sample and environmental control .....	9
5.4	Taking samples from the bulk material .....	9
5.5	Moisture content .....	10
5.6	Bulk density .....	10
5.7	Test procedure .....	10
5.8	Replicate tests .....	10
5.9	In-house test powder .....	10
5.10	Reporting .....	10
6	Test methods .....	10
6.1	Description of the methods .....	10
6.2	Selection of the most appropriate test method .....	11
7	Evaluation of dustiness .....	11
8	Test report .....	12
Annex A (normative) Determination of moisture content .....		13
Annex B (normative) Determination of bulk density of the test material .....		15
Annex C (informative) Spheriglass 5000 CP00 - An example of a suitable powder for quality purposes .....		16
Bibliography .....		17