

# ISO 15202-2:2001-07 (E)

## Workplace air - Determination of metals and metalloids in airborne particulate matter by inductively coupled plasma atomic emission spectrometry - Part 2: Sample preparation

---

<b>Contents</b>	<b>Page</b>
Foreword .....	iv
Introduction .....	v
1 Scope .....	1
2 Normative references .....	2
3 Terms and definitions .....	2
4 Principle .....	3
5 Requirements .....	4
6 Reactions .....	4
7 Reagents .....	4
8 Laboratory apparatus .....	4
9 Procedure .....	5
9.1 Soluble metal and metalloid compounds .....	5
9.2 Total metals and metalloids and their compounds .....	5
9.3 Mixed exposure .....	5
10 Special cases .....	6
10.1 Action to be taken if there is doubt about the effectiveness of the selected sample dissolution method .....	6
10.2 Action to be taken when particles have become dislodged from the filter during transportation .....	6
11 Laboratory records .....	6
Annex A (informative) Safety precautions to be observed when using hydrofluoric and perchloric acids .....	7
Annex B (normative) Sample dissolution method for soluble metal and metalloid compounds .....	8
Annex C (normative) Sample dissolution using nitric acid and hydrochloric acid on a hotplate .....	14
Annex D (normative) Sample dissolution using hydrofluoric and nitric acids and ultrasonic agitation .....	17
Annex E (normative) Sample dissolution based on the use of sulfuric acid and hydrogen peroxide on a hotplate .....	20
Annex F (normative) Sample dissolution based on the use of nitric acid and perchloric acid on a hotplate .....	24

<b>Annex G (normative) Sample dissolution in a closed vessel microwave digestion system .....</b>	<b>28</b>
<b>Annex H (normative) Action to be taken when there is visible, undissolved, particulate material after sample dissolution .....</b>	<b>33</b>
<b>Bibliography .....</b>	<b>37</b>