

DIN EN 1093-2:2007-03 (E)

Safety of machinery - Evaluation of the emission of airborne hazardous substances - Part 2: Tracer gas method for the measurement of the emission rate of a given pollutant

Contents		Page
Foreword		3
Introduction		4
1	Scope	5
2	Normative references	5
3	Terms and definitions	5
4	Principle	5
5	Location of the machine	5
6	Apparatus and materials	6
7	Measurement points	7
8	Procedure	8
9	Data analysis	8
10	Expression of results	9
11	Test report	10
Annex ZA (informative) Relationship between this European Standard and the Essential Requirements of EU Directive 98/37/EC		12