

### Contents

|         |   |
|---------|---|
|         | Foreword  |
|         | Introduction  |
| 1       | Scope   |
| 2       | Normative references  |
| 3       | Terms and definitions   |
| 3.1     | General terms and definitions                                 |
| 3.2     | Classification codes for drawings and data sets (see Annex B) |
| 4       | Data set identification and control                           |
| 4.1     | General   |
| 4.2     | Related data  |
| 4.3     | Data management   |
| 5       | Data set requirements   |
| 5.1     | General   |
| 5.1.1   | Introduction  |
| 5.1.2   | Fundamental requirements                                      |
| 5.1.2.1 | General   |
| 5.1.2.2 | Common to annotated models and drawings                       |
| 5.1.2.3 | Applicable only to models                                     |
| 5.1.2.4 | Applicable only to drawings accompanied by 3D models          |
| 5.1.3   | Design model requirement (classification codes 3, 4 and 5)    |
| 5.2     | General model requirements                                    |
| 5.2.1   | Associativity   |
| 5.2.2   | Model coordinate systems                                      |
| 5.2.3   | Applications of supplemental geometry                         |
| 5.2.4   | Part features not fully modelled                              |
| 5.3     | General method requirements                                   |
| 5.3.1   | Data set methods  |
| 5.3.2   | Model-only method   |
| 5.3.3   | Model and drawing method                                      |
| 5.4     | Management data   |
| 5.4.1   | General   |
| 5.4.2   | Management data in the data set                               |
| 5.4.3   | Management data on a model                                    |
| 5.5     | Protection marking  |
| 5.5.1   | General   |
| 5.5.2   | Location on models  |
| 5.6     | Saved views on models   |
| 5.6.1   | General   |
| 5.6.2   | Sections  |
| 6       | Design model requirements                                     |
| 6.1     | General   |
| 6.2     | Geometric scale, units and precision                          |
| 6.3     | Model completeness  |
| 6.4     | Assembly model completeness                                   |
| 6.5     | Part reference numbers  |
| 6.6     | Identification method   |
| 6.6.1   | General   |
| 6.6.2   | Colour  |

- 6.6.3 Greyscale
- 6.6.4 Mapping
- 6.6.5 Transparency
- 6.7 Installation model completeness
- 7 Common requirements for product definition data
  - 7.1 General
  - 7.2 Common requirements
  - 7.3 Model requirements
    - 7.3.1 General
    - 7.3.2 Associativity
    - 7.3.3 Attributes
    - 7.3.4 Annotation planes
    - 7.3.5 Leader lines
    - 7.3.6 Direction-dependent specifications
    - 7.3.7 Indicating of restricted area
    - 7.3.8 Query types
  - 7.4 Drawing requirements
    - 7.4.1 General
    - 7.4.2 Orthographic views
    - 7.4.3 Axonometric views
- 8 Notes and special notations
  - 8.1 Common requirements
  - 8.2 Model requirements
  - 8.3 Drawing requirements
- 9 Model values and dimensions
  - 9.1 General
  - 9.2 Common requirements
    - 9.2.1 Model value queries
    - 9.2.2 Resolved dimensions
  - 9.3 Model requirements
    - 9.3.1 General
    - 9.3.2 Theoretically exact dimensions (TEDs)
    - 9.3.3 Size values
    - 9.3.4 Examples of general applications
    - 9.3.5 Chamfers
    - 9.3.6 Depth specification
  - 9.4 Drawing requirements for axonometric views
- 10 Datum applications
  - 10.1 General
  - 10.2 Model requirements
    - 10.2.1 Datum systems and model coordinate systems
      - 10.2.1.1 Introduction
      - 10.2.1.2 Datum system and coordinate system correspondence
      - 10.2.1.3 Display link between datum system and coordinate system
    - 10.2.2 Identification of datums
    - 10.2.3 Identification of restricted area application
    - 10.2.4 Associativity of datum features and design data
    - 10.2.5 Datum target identification and attachment
    - 10.2.6 Multiple features establishing a datum
  - 10.3 Drawing requirements
- 11 Geometric tolerances
  - 11.1 General
  - 11.2 Drawing requirements
    - 11.2.1 General
- 12 Welds
  - 12.1 General
  - 12.2 Common requirements
    - 12.2.1 Application of supplemental geometry

- 12.2.2 Arrow lines
- 12.3 Model requirements
  - 12.3.1 Annotation plane
  - 12.3.2 Associativity
  - 12.3.3 Indicating extents of the weld
  - 12.3.4 Query of weld path
- 12.4 Drawing requirements
- 13 Surface texture
  - 13.1 General
  - 13.2 Common requirements
  - 13.3 Model requirements
    - 13.3.1 Display techniques
    - 13.3.2 Associativity
- Annex A (informative) Former practices
  - A.1 General
  - A.2 Direction-dependant tolerances
    - A.2.1 General
    - A.2.2 Represented line element
  - A.3 Orientation tolerances
- Annex B (informative) Classification codes for drawings and data sets
  - B.1 General
  - B.2 Application
  - B.3 Definitions
  - B.4 Classification code requirements
    - B.4.1 General
    - B.4.2 Classification code location
    - B.4.3 Classification code 1
    - B.4.4 Classification code 2
    - B.4.5 Classification code 3
    - B.4.6 Classification code 4
    - B.4.7 Classification code 5
- Annex C (informative) Examples
  - C.1 General
  - C.2 Examples
    - C.2.1 Usage of “between” symbol
    - C.2.2 All-around application
    - C.2.3 Conical surface and surface of revolution

Page count: 76