

ISO 29863:2007-12 (E)

Self adhesive tapes — Measurement of static shear adhesion

Contents

	page
Foreword.....	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions.....	5
4 Significance and use	5
5 Method A: Measurement of shear adhesion to a vertical standard steel panel	6
5.1 Principle	6
5.2 Materials.....	6
5.3 Apparatus	6
5.4 Test samples and test piece	7
5.5 Procedure	8
5.6 Expression of results	9
5.7 Test report	9
6 Method B: Measurement of shear adhesion to a vertical panel covered with NIST SRM 1810A standard fibreboard	9
6.1 Principle	9
6.2 Materials.....	9
6.3 Apparatus	10
6.4 Test samples and test piece	10
6.5 Procedure	10
6.6 Expression of results	10
6.7 Test report	10
7 Method C: Measurement of shear adhesion to a vertical panel covered with a fibreboard agreed upon by the buyer and the seller.....	11
7.1 Principle.....	11
7.2 Procedure	11
8 Method D: Measurement of shear adhesion of filament reinforced tape applied to a horizontal standard steel panel	11
8.1 Principle	11
8.2 Materials.....	11
8.3 Apparatus	11
8.4 Test samples and test piece	12
8.5 Procedure	12
8.6 Expression of results	13
8.7 Test report	13
9 Method E: Measurement of shear adhesion of filament reinforced tape applied to a horizontal panel covered with NIST SRM 1810A standard fibreboard	13
9.1 Principle.....	13
9.2 Procedure	13
10 Method F: Measurement of shear adhesion of filament reinforced tape applied to a horizontal panel covered with a fibreboard agreed upon by the buyer and the seller	14
10.1 Principle.....	14
10.2 Procedure	14
11 Method G: Measurement of shear adhesion to a vertical standard steel panel at an elevated temperature after 10 min dwell time.....	14
11.1 Principle	14
11.2 Procedure	14