

# ISO 10704:2019 (E)

## Water quality — Gross alpha and gross beta activity — Test method using thin source deposit

---

### Contents

|         |   |
|---------|---|
|         | Foreword  |
|         | Introduction  |
| 1       | Scope   |
| 2       | Normative references  |
| 3       | Terms, definitions and symbols                                      |
| 4       | Principle   |
| 5       | Chemical reagents and equipment                                     |
| 5.1     | Reagents  |
| 5.1.1   | General   |
| 5.1.2   | Standard solutions  |
| 5.1.3   | Wetting or surfactant agents  |
| 5.1.4   | Volatile organic solvents   |
| 5.1.5   | Water   |
| 5.1.6   | Specific reagents for alpha-emitting radionuclides co-precipitation |
| 5.2     | Equipment   |
| 5.2.1   | Laboratory equipment for direct evaporation                         |
| 5.2.2   | General equipment   |
| 5.2.3   | Special equipment for alpha-emitting radionuclide co-precipitation  |
| 5.2.4   | Measurement equipment   |
| 6       | Sampling  |
| 7       | Procedure   |
| 7.1     | Preliminary   |
| 7.2     | Source preparation  |
| 7.2.1   | Preparation of planchet   |
| 7.2.2   | Evaporation   |
| 7.2.3   | Co-precipitation  |
| 7.3     | Counting stage  |
| 7.4     | Background and blank determination                                  |
| 7.5     | Preparation of counting standard for calibration                    |
| 7.6     | Preparation of calibration source for self-absorption determination |
| 7.6.1   | General   |
| 7.6.2   | Spiking one of two test portions                                    |
| 7.6.3   | Self-absorption curve   |
| 7.6.3.1 | Alpha self-absorption correction                                    |
| 7.6.3.2 | Beta self-absorption correction                                     |
| 8       | Expression of results   |
| 8.1     | General   |
| 8.2     | Alpha activity concentration  |
| 8.3     | Beta activity concentration   |
| 8.4     | Standard uncertainty of the alpha activity concentration            |
| 8.5     | Standard uncertainty of the beta activity concentration             |
| 8.6     | Decision threshold  |
| 8.6.1   | Decision threshold of the alpha activity concentration              |
| 8.6.2   | Decision threshold of the beta activity concentration               |

|         |   |
|---------|---|
| 8.7     | Detection limit                                     |
| 8.7.1   | Detection limit of the alpha activity concentration |
| 8.7.2   | Detection limit of the beta activity concentration  |
| 8.8     | Confidence limits                                   |
| 9       | Control of interferences                            |
| 9.1     | General   |
| 9.2     | Relative humidity                                   |
| 9.3     | Geometry of the deposit                             |
| 9.4     | Crosstalk   |
| 9.5     | Gamma emitters                                      |
| 9.6     | Low beta energy                                     |
| 9.7     | Chlorides   |
| 9.8     | Organic matter                                      |
| 9.9     | Contamination                                       |
| 9.10    | Losses of activity                                  |
| 9.11    | Contribution of the natural radionuclides           |
| 9.12    | Losses of activity                                  |
| 10      | Test report   |
| Annex A | (informative) Numerical applications                |

Page count: 20