

# ISO 4722-2:2024-12 (E)

## Water quality - Thorium 232 - Part 2: Test method using ICP-MS

---

<b>Contents</b>		<b>Page</b>
Foreword		iv
Introduction		v
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative references</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions</b>	<b>2</b>
<b>4</b>	<b>Symbols</b>	<b>2</b>
<b>5</b>	<b>Principle</b>	<b>3</b>
<b>6</b>	<b>Sampling and sample storage</b>	<b>5</b>
<b>7</b>	<b>Chemical reagents and apparatus</b>	<b>5</b>
	7.1 General	5
	7.2 Chemical reagents	5
	7.3 Apparatus	5
<b>8</b>	<b>Separation</b>	<b>6</b>
<b>9</b>	<b>Quality control</b>	<b>6</b>
	9.1 General	6
	9.2 Variables that can influence the measurement	6
	9.3 Instrument verification	6
	9.4 Method verification	7
<b>10</b>	<b>Expression of results</b>	<b>7</b>
	10.1 Data analysis	7
	10.2 Background	8
	10.3 Internal standard	8
	10.4 Expression of results using $^{229}\text{Th}$ or $^{230}\text{Th}$ as a recovery tracer by ICP-MS	8
	10.4.1 Calculation of activity of tracer and mass of analyte	8
	10.4.2 Measurement bias	9
	10.4.3 Sample mass concentration	9
	10.5 Expression of results using $^{229}\text{Th}$ or $^{230}\text{Th}$ as a recovery tracer	9
	10.5.1 Calculation of activity of tracer and mass of analyte	9
	10.5.2 Chemical recovery	10
	10.5.3 Measurement bias	10
	10.5.4 Sample mass concentration of the analyte	11
	10.6 Limit of detection	11
	10.7 Limit of quantification	11
	10.8 Correcting for $^{232}\text{Th}$ contamination in the tracer	11
	10.9 Conversion of mass concentration to mass activity	12
	10.10 Conversion from mass to volume units	12
<b>11</b>	<b>Test report</b>	<b>12</b>
<b>Annex A (informative) Chemical separation of thorium</b>		<b>14</b>
<b>Bibliography</b>		<b>17</b>