

ISO 3547-7:2007-10 (E)

Plain bearings - Wrapped bushes - Part 7: Measurement of wall thickness of thin-walled bushes

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and units	2
5	Purpose of checking	2
6	Checking methods	2
7	Requirements for measuring equipment for the contact method	5
8	Checking of measuring equipment	5
Bibliography		6