

# ISO 12308:2017-04 (E)

## Plain bearings - Quality assurance of sample types - Definitions, applications and testing

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Inspection and test report for samples</b> .....	<b>1</b>
<b>5</b>	<b>Marking</b> .....	<b>2</b>
<b>6</b>	<b>Types of plain bearing samples, definition and manufacturing process, application and testing</b> .....	<b>2</b>
<b>7</b>	<b>Designation</b> .....	<b>2</b>
<b>Bibliography</b> .....		<b>4</b>