

# ISO 3547-6:2020-05 (E)

## Plain bearings - Wrapped bushes - Part 6: Checking the inside diameter

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b>	.....	<b>iv</b>
<b>Introduction</b>	.....	<b>v</b>
<b>1 Scope</b>	.....	<b>1</b>
<b>2 Normative references</b>	.....	<b>1</b>
<b>3 Terms and definitions</b>	.....	<b>1</b>
<b>4 Symbols and units</b>	.....	<b>1</b>
<b>5 Method of checking</b>	.....	<b>2</b>
<b>6 Test equipment</b>	.....	<b>2</b>
6.1 Ring gauge	.....	2
6.2 Plug gauge	.....	3
6.3 Three-point measuring instrument	.....	4
6.4 Requirements for measuring equipment	.....	5
6.5 Measuring errors	.....	5
<b>7 Procedure</b>	.....	<b>5</b>
<b>Bibliography</b>	.....	<b>6</b>