

# DIN EN 1014-2:2010-11 (E)

## Wood preservatives - Creosote and creosoted timber - Methods of sampling and analysis - Part 2 : Procedure for obtaining a sample of creosote from creosoted timber for subsequent analysis

---

<b>Contents</b>		<b>Page</b>
	<b>Foreword</b> .....	<b>3</b>
<b>1</b>	<b>Scope</b> .....	<b>4</b>
<b>2</b>	<b>Normative references</b> .....	<b>4</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>4</b>
<b>4</b>	<b>Sampling</b> .....	<b>4</b>
<b>4.1</b>	<b>General</b> .....	<b>4</b>
<b>4.2</b>	<b>Sampling procedure</b> .....	<b>4</b>
<b>4.3</b>	<b>Amount of sample</b> .....	<b>4</b>
<b>5</b>	<b>Reagent</b> .....	<b>5</b>
<b>6</b>	<b>Apparatus</b> .....	<b>5</b>
<b>7</b>	<b>Procedure for the extraction of creosote from the sample of the creosoted timber</b> .....	<b>7</b>
<b>8</b>	<b>Sampling report</b> .....	<b>7</b>
	<b>Bibliography</b> .....	<b>8</b>