

# ISO/IEC TR 24720:2008-06 (E)

## Information technology - Automatic identification and data capture techniques - Guidelines for direct part marking (DPM)

---

| <b>Contents</b>   |   | <b>Page</b> |
|---|---|-------------|
| Foreword .....  |   | iv          |
| Introduction .....  |   | v           |
| 1   | Scope .....   | 1           |
| 2   | Normative references .....                                    | 1           |
| 3   | Terms and definitions .....                                   | 1           |
| 4   | Abbreviated terms .....                                       | 2           |
| 5   | Overview of DPM .....   | 2           |
| 5.1   | DPM methods .....   | 2           |
| 5.2   | Reasons for utilizing DPM .....                               | 3           |
| 6   | Marking method selection .....                                | 3           |
| 7   | Marking methods .....   | 6           |
| 8   | Cleaning .....  | 6           |
| 9   | Marking surface preparation .....                             | 6           |
| 9.1   | Assessment .....  | 6           |
| 9.2   | Protective coatings .....                                     | 7           |
| 10  | Human readable marking .....                                  | 8           |
| 11  | Symbol quality .....  | 8           |
| 12  | Reading and grading DPM symbols .....                         | 9           |
| 13  | Verification .....  | 9           |
| 13.1  | General .....   | 9           |
| 13.2  | Configuration .....   | 9           |
| 13.3  | Possible equipment setup .....                                | 10          |
| 14  | Imagers for direct part marking applications .....            | 11          |
| 14.1  | General description .....                                     | 11          |
| 14.2  | Fixed-mount imagers .....                                     | 11          |
| 14.3  | Presentation imager .....                                     | 12          |
| 14.4  | Hand-held imager .....  | 12          |
| Annex A (informative) Intrusive marking methods .....     |   | 14          |
| A.1   | Intrusive marking .....                                       | 14          |
| A.2   | Re-marking requirements using intrusive marking methods ..... | 15          |
| A.3   | Laser marking .....   | 15          |
| A.4   | Dot peen marking .....  | 18          |
| A.5   | Other Intrusive marking methods .....                         | 20          |
| Annex B (informative) Non-intrusive marking methods ..... |   | 22          |
| B.1   | Non-intrusive marking methods .....                           | 22          |
| B.2   | Ink jet marking .....   | 22          |

|  |  |           |
|--|--|-----------|
| <b>B.3</b>   | <b>Fabric embroidery/weaving</b> .....           | <b>25</b> |
| <b>B.4</b>   | <b>Forge, cast</b> .....                         | <b>26</b> |
| <b>B.5</b>   | <b>Laser bonding</b> .....                       | <b>27</b> |
| <b>B.6</b>   | <b>Laser engineered net shaping (LENS)</b> ..... | <b>27</b> |
| <b>B.7</b>   | <b>Screen printing</b> .....                     | <b>28</b> |
| <b>B.8</b>   | <b>Stencil</b> .....                             | <b>29</b> |
| <b>Annex C (informative) Rockwell Hardness</b> ..... |  | <b>30</b> |
| <b>Bibliography</b> .....                            |  | <b>32</b> |