

# ISO/IEC 29121:2009-02 (E)

## Information technology - Digitally recorded media for information interchange and storage - Data migration method for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	2
4	Test methods .....	3
4.1	Test parameters .....	3
4.2	Test Drive .....	3
4.2.1	Test drive calibration .....	3
4.2.2	Test preparation .....	4
4.2.3	Test execution .....	4
4.3	Test area .....	4
5	Test result evaluation .....	4
5.1	Initial performance test result evaluation .....	4
5.2	Periodical performance test result evaluation .....	5
6	Test frequency .....	6
7	Prevention of deterioration .....	6
Annex A (informative) Causes of deterioration for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks ...		7
A.1	Deterioration .....	7
A.2	Disk structure .....	7
A.3	Causes of deterioration .....	7
A.4	Nature of deterioration .....	8
A.5	Effects of deterioration .....	8
Annex B (informative) Recommendations on handling, storage and cleaning conditions for DVD-R, DVD-RW, DVD-RAM, +R, and +RW disks .....		9
B.1	Handling .....	9
B.2	Storage .....	9
B.3	Cleaning .....	10
Annex C (informative) Relation between BER and PIE SUM 8 .....		11
Annex D (informative) Normalization of the time scales .....		12
Annex E (informative) Test area .....		14
Bibliography .....		15