

# ISO 15872:2017-03 (E)

## Aerospace - UNJ threads - Gauging

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions, symbols and abbreviated terms .....</b>	<b>1</b>
3.1	Terms and definitions .....	1
3.2	Symbols and abbreviated terms .....	2
<b>4</b>	<b>Types of gauges .....</b>	<b>3</b>
4.1	Gauges and setting plugs for external threaded products .....	3
4.2	Gauges for internal threaded products .....	3
<b>5</b>	<b>Reference temperature .....</b>	<b>3</b>
<b>6</b>	<b>Function, design and use of gauges .....</b>	<b>4</b>
6.1	Gauges for external threads .....	4
6.1.1	Virtual pitch diameter indicating thread gauges .....	4
6.1.2	Solid or adjustable GO screw ring gauges .....	4
6.1.3	Simple pitch diameter indicating thread gauges .....	4
6.1.4	Major diameter gauges .....	5
6.1.5	Minor diameter gauges .....	5
6.1.6	Optical comparator checks .....	5
6.2	Gauging for internal threads .....	5
6.2.1	GO screw plug gauges .....	5
6.2.2	NOT GO screw plug gauges .....	5
6.2.3	Minor diameter gauges .....	5
6.2.4	Virtual pitch diameter indicating thread gauges .....	5
6.2.5	Simple pitch diameter indicating thread gauges .....	6
<b>7</b>	<b>Setting of gauges .....</b>	<b>6</b>
7.1	Setting gauges for external threads .....	6
7.2	Setting ring gauge for indication thread gauges .....	6
<b>8</b>	<b>Gauging of threads .....</b>	<b>6</b>
8.1	General .....	6
8.2	Internal threads evaluation .....	7
Bibliography .....		22