

# ISO 15872:2017-03 (E)

## Aerospace - UNJ threads - Gauging

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions, symbols and abbreviated terms .....</b>	<b>1</b>
<b>3.1</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.2</b>	<b>Symbols and abbreviated terms .....</b>	<b>2</b>
<b>4</b>	<b>Types of gauges .....</b>	<b>3</b>
<b>4.1</b>	<b>Gauges and setting plugs for external threaded products .....</b>	<b>3</b>
<b>4.2</b>	<b>Gauges for internal threaded products .....</b>	<b>3</b>
<b>5</b>	<b>Reference temperature .....</b>	<b>3</b>
<b>6</b>	<b>Function, design and use of gauges .....</b>	<b>4</b>
<b>6.1</b>	<b>Gauges for external threads .....</b>	<b>4</b>
<b>6.1.1</b>	<b>Virtual pitch diameter indicating thread gauges .....</b>	<b>4</b>
<b>6.1.2</b>	<b>Solid or adjustable GO screw ring gauges .....</b>	<b>4</b>
<b>6.1.3</b>	<b>Simple pitch diameter indicating thread gauges .....</b>	<b>4</b>
<b>6.1.4</b>	<b>Major diameter gauges .....</b>	<b>5</b>
<b>6.1.5</b>	<b>Minor diameter gauges .....</b>	<b>5</b>
<b>6.1.6</b>	<b>Optical comparator checks .....</b>	<b>5</b>
<b>6.2</b>	<b>Gauging for internal threads .....</b>	<b>5</b>
<b>6.2.1</b>	<b>GO screw plug gauges .....</b>	<b>5</b>
<b>6.2.2</b>	<b>NOT GO screw plug gauges .....</b>	<b>5</b>
<b>6.2.3</b>	<b>Minor diameter gauges .....</b>	<b>5</b>
<b>6.2.4</b>	<b>Virtual pitch diameter indicating thread gauges .....</b>	<b>5</b>
<b>6.2.5</b>	<b>Simple pitch diameter indicating thread gauges .....</b>	<b>6</b>
<b>7</b>	<b>Setting of gauges .....</b>	<b>6</b>
<b>7.1</b>	<b>Setting gauges for external threads .....</b>	<b>6</b>
<b>7.2</b>	<b>Setting ring gauge for indication thread gauges .....</b>	<b>6</b>
<b>8</b>	<b>Gauging of threads .....</b>	<b>6</b>
<b>8.1</b>	<b>General .....</b>	<b>6</b>
<b>8.2</b>	<b>Internal threads evaluation .....</b>	<b>7</b>
<b>Bibliography .....</b>		<b>22</b>