

DIN EN 16602-70-61:2023-01 (E)

Space product assurance - High-reliability soldering for surface mount, mixed technology and hand-mounted electrical connections; English version EN 16602-70-61:2022

Contents	Page
European Foreword	13
Introduction	14
1 Scope	21
2 Normative references	22
3 Terms, definitions and abbreviated terms	24
3.1 Terms from other standards.....	24
3.2 Terms specific to the present standard	24
3.3 Abbreviated terms.....	29
3.4 Nomenclature	31
4 Principles of reliable soldered connections	32
5 Preparatory conditions	33
5.1 Facility cleanliness.....	33
5.2 Environmental conditions.....	33
5.3 Lighting requirements	34
5.4 Precautions against static discharges.....	34
5.4.1 Overview.....	34
5.4.2 General.....	35
5.4.3 ESD Protected Area.....	35
5.4.4 Precautions against ESD during manufacturing	36
5.4.5 Protective packaging and ESD protection	37
5.5 Equipment and tools.....	37
5.5.1 General.....	37
5.5.2 Brushes.....	38
5.5.3 Cutters and pliers.....	38
5.5.4 Bending tools	39
5.5.5 Clinching tools.....	39
5.5.6 Insulation strippers.....	40
5.5.7 Hot air blower.....	41

5.5.8	Soldering tools	41
5.5.9	Baking and curing ovens	42
5.5.10	Solder deposition equipment.....	43
5.5.11	Automatic component placement equipment.....	43
5.5.12	Dynamic wave-solder machines.....	43
5.5.13	Selective wave solder equipment.....	44
5.5.14	Reflow process equipment.....	45
5.5.15	Depanelization tool.....	47
5.5.16	Cleanliness testing equipment	47
5.5.17	Optical microscope.....	47
5.5.18	Automatic Optical Inspection (AOI) equipment.....	47
5.5.19	X-ray inspection equipment.....	47
6	Material selection	49
6.1	General.....	49
6.2	Solder	49
6.2.1	Form	49
6.2.2	Composition.....	50
6.2.3	Storage and handling of paste purity.....	52
6.3	Fluxes.....	52
6.3.1	Rosin based fluxes.....	52
6.4	Solvents.....	53
6.5	Flexible insulation materials.....	54
6.6	Terminals.....	54
6.6.1	Materials	54
6.6.2	Tin, silver, and gold-plated terminals.....	54
6.7	Wires	55
6.8	Sculptured flex.....	55
6.9	Printed circuits substrates.....	55
6.9.1	Substrates selection.....	55
6.9.2	Gold finish on PCBs footprint	55
6.9.3	PCB design requirements for wave and selective wave soldering.....	56
6.10	Components	56
6.10.1	General	56
6.10.2	Moisture sensitive components	57
6.11	Adhesives, potting, underfill and conformal coatings.....	57
7	Preparations prior to mounting and soldering	58

7.1	General handling	58
7.2	Storage.....	58
7.2.1	Components.....	58
7.2.2	PCBs.....	58
7.2.3	Materials requiring segregation	58
7.3	Baking conditions of PCBs.....	59
7.4	Baking and storage of moisture sensitive components	59
7.5	Preparation of components, wires, terminals, and solder cups.....	60
7.5.1	Damage to insulation	60
7.5.2	Damage to conductors and braid	60
7.5.3	Cleaning before soldering	61
7.5.4	Insulation clearance	61
7.5.5	Wire lay.....	61
7.6	Degolding and pretinning.....	61
7.6.1	General.....	61
7.6.2	Solder baths method for degolding and pretinning of components terminations and terminals	62
7.6.3	Solder iron method for degolding and pretinning	64
7.6.4	Pretinning processes.....	64
7.7	Preparation of the soldering tip	65
8	Components mounting requirements prior to soldering	67
8.1	General requirements.....	67
8.2	Mounting of through hole components	67
8.2.1	General.....	67
8.2.2	Heavy components	68
8.2.3	Metal-case components	68
8.2.4	Glass-encased components.....	68
8.2.5	Stress relief of components with bendable leads.....	68
8.2.6	Stress relief of components with non-bendable leads.....	71
8.2.7	Bending of component leads.....	72
8.2.8	Lead attachment to PCBs	73
8.2.9	Mounting of through hole connectors to PCBs	76
8.2.10	Mounting of swage terminals to PCBs.....	77
8.2.11	Mounting of components to terminals.....	78
8.3	Mounting of surface mount components	79
8.3.1	General.....	79
8.3.2	Lead forming	80

8.3.3	Inspection of solder paste deposition	80
9	Attachment of conductors to terminals, solder cups and cables	81
9.1	General.....	81
9.2	Wire termination	81
9.2.1	Breakouts from cables	81
9.2.2	Insulation clearance	82
9.3	Turret and straight-pin terminals	82
9.4	Bifurcated terminals	83
9.4.1	General.....	83
9.4.2	Bottom route	83
9.4.3	Side route	84
9.4.4	Top route	85
9.4.5	Combination of top and bottom routes.....	86
9.4.6	Combination of side and bottom routes	86
9.5	Hook terminals.....	86
9.6	Pierced terminals.....	87
9.7	Solder cups for connector	87
9.8	Insulation sleeving	88
9.9	Wire and cable interconnections	89
9.9.1	General.....	89
9.9.2	Preparation of wires	89
9.9.3	Preparation of shielded wires and cables	90
9.9.4	Pre-assembly of wires.....	90
9.10	Connection of wires to PCBs	91
9.11	Connection of coaxial cables to PCBs	93
10	Assembly to terminals and to PCBs	94
10.1	Overview	94
10.2	General soldering conditions	94
10.2.1	General.....	94
10.2.2	Positioning	95
10.2.3	Application of flux.....	96
10.2.4	Flux controls for wave-soldering equipment	97
10.2.5	Soldering temperatures.....	97
10.2.6	Soldering of conductors in terminals	99
10.3	Soldering of components, terminals, and wires into PCB through holes.....	100
10.3.1	General.....	100

10.3.2	Solder fillets for wires and terminations	100
10.3.3	Solder fillets for component leads in plated or non-plated through holes	101
10.4	Soldering of surface mount components	102
10.4.1	General	102
10.4.2	Rectangular and square end-capped or end-metallized leadless chip	104
10.4.3	Cylindrical and square end-capped components with cylindrical or oval body	106
10.4.4	Bottom terminated chip components	107
10.4.5	L-Shape inwards components	109
10.4.6	Leadless component with plane termination	110
10.4.7	Leaded component with plane termination	110
10.4.8	Leadless castellated ceramic chip carrier components	112
10.4.9	No lead Quad Flat Pack	113
10.4.10	Flat pack and gull-wing leaded components with round, rectangular, ribbon leads	115
10.4.11	Components with "J" leads	116
10.4.12	Components with ribbon terminals without stress relief	117
10.4.13	Stacked modules components with leads protruding vertically from bottom	119
10.4.14	Area array devices	120
10.5	Rework and repair	122
10.5.1	Removal of solder on unpopulated PCB	122
10.5.2	Rework, repair and modifications	122
10.6	High-voltage connections	123
10.7	Solderless components	125
11	Post soldering process requirements	126
11.1	Cleaning of PCB assemblies	126
11.1.1	General	126
11.1.2	Verification of cleanliness	127
11.1.3	Surface Insulation Resistance (SIR) testing	127
11.1.4	Sodium chloride (NaCl) equivalent ionic contaminants testing	128
11.1.5	Monitoring of cleanliness	129
11.2	Staking and bonding	129
11.3	Conformal coating, potting and underfill	130
12	Final inspection	132
12.1	General	132
12.2	Visual acceptance criteria	132

12.3	Visual rejection criteria.....	133
12.4	X-ray rejection criteria.....	135
12.5	Warp and twist of populated boards.....	136
12.6	Inspection records	136
13	Verification procedure.....	137
13.1	Verification approval procedure	137
13.1.1	Request for verification	137
13.1.2	Technology sample.....	137
13.1.3	Audit of assembly processing.....	138
13.1.4	Verification programme documentation	138
13.1.5	Verification samples and testing.....	139
13.1.6	Final verification review	140
13.1.7	Approval status of assembly line	140
13.1.8	Withdrawal of approval status	141
13.2	Verification programme.....	141
13.2.1	General.....	141
13.2.2	Verification for PTH manual soldering	147
13.2.3	Additional verification for wave soldering.....	147
13.2.4	Soldering log	147
13.3	Special verification testing for ceramic area array components.....	149
13.3.1	General.....	149
13.3.2	Evaluation of AAD capability samples	151
13.3.3	Electrical verification of AAD assembly	151
13.4	Assembly verification with electrical testing procedure.....	152
13.5	Verification programme with reduced temperature range.....	155
13.6	Verification for solderless process	156
13.7	Conditions for delta verification	158
13.8	Verification by similarity	160
13.8.1	General conditions for similarity	160
13.8.2	Conditions for similarity for PTH components.....	160
13.8.3	Conditions for similarity for SMD	161
13.8.4	Conditions for similarity for solderless components.....	164
14	Environmental tests conditions	165
14.1	Overview	165
14.2	Visual inspection.....	165
14.3	X-ray inspection.....	165

14.4	Cleanliness test	165
14.5	Warp and twist of PCB.....	165
14.6	Electrical continuity measurement	166
14.7	Electrical continuity for wave soldered multilayers PCB	166
14.8	Vibration	167
14.9	Mechanical shock	169
14.10	Damp heat test	171
14.11	Temperature cycling test.....	171
14.12	Temperature cycling test with reduced temperature range.....	172
14.13	Life test.....	174
14.14	Final visual inspection.....	174
14.15	Microsection	175
14.15.1	Microsection facilities	175
14.15.2	Microsections location.....	175
14.15.3	Microsection acceptance criteria	176
14.15.4	Microsection acceptance criteria for ceramic chip capacitors	189
14.16	Anomalies in PCB and sculptured flex during verification.....	196
15	Outsourcing	197
15.1	General.....	197
16	Process identification document (PID)	199
16.1	Overview	199
16.2	Document preparation	199
16.3	Approval	199
16.4	Contact person	199
16.5	Process identification document update.....	199
17	Quality assurance.....	200
17.1	General.....	200
17.2	Data.....	200
17.3	Nonconformance	200
17.4	Calibration	200
17.5	Traceability	201
17.6	Workmanship standards	201
17.7	Inspection points.....	201
17.8	Operators, inspectors and instructors training and certification	201
Annex A	(normative) Verification programme - DRD	203
A.1	DRD identification.....	203

A.2	Expected response	203
Annex B (normative)	Verification report - DRD	205
B.1	DRD identification	205
B.2	Expected response	205
Annex C (normative)	Process Identification Documentation (PID) - DRD	207
C.1	DRD identification	207
C.2	Expected response	207
Annex D (normative)	Assembly Summary Table - DRD	210
D.1	DRD identification	210
D.2	Expected response	210
Annex E (normative)	Visual workmanship standards for through hole component	212
E.1	Soldered stud terminals	212
E.2	Soldered turret terminals.....	213
E.3	Soldered bifurcated terminals	215
E.4	Soldered hook terminals	216
E.5	Soldered cup terminals	217
E.6	Miscellaneous examples of soldered wires	218
E.7	Soldered wire to shielded cable interconnections	219
E.8	Assembly of Dual in Line Package.....	221
Annex F (informative)	Visual and X-ray workmanship standards for SMDs	222
F.1	Workmanship illustrations for standard SMDs.....	222
F.2	X Ray Workmanship illustrations for solder flow and voids	238
F.3	X Ray Workmanship illustrations for ball grid array devices	239
F.4	Workmanship illustrations for column grid array devices.....	240
Annex G (informative)	Example of an SMT audit report.....	242
Annex H (informative)	Solder Alloys melting temperatures and choice.....	251
H.1	Melting temperatures and choice	251
Bibliography.....		252
 Figures		
Figure 5-1:	Profile of correct cutters for trimming leads.....	39
Figure 5-2:	Example of suitable mechanical strippers.....	40
Figure 8-1:	Assembly of TO-39 and CKR06	70

Figure 8-2: TO package with underfill	70
Figure 8-3: Methods for incorporating stress relief with components having bendable leads	71
Figure 8-4: Methods for attaching wire extensions to non-bendable leads.....	72
Figure 8-5: Minimum lead bend	73
Figure 8-6: Stud leads	74
Figure 8-7: Wires used to connect opposite sides of a PCB	75
Figure 8-8: Clinching with stress relief for component in non-plated hole	76
Figure 8-9: Types of terminal swaging.....	78
Figure 8-10: Method of stress relieving components attached to terminals.....	78
Figure 8-11: Exposed element.....	79
Figure 9-1: Side route connections to turret terminals	83
Figure 9-2: Bottom route connections to bifurcated terminal.....	84
Figure 9-3: Side-route connection to bifurcated terminal.....	85
Figure 9-4: Top route connection to bifurcated terminal.....	85
Figure 9-5: Connections to hook terminals	86
Figure 9-6: Connections to pierced terminals	87
Figure 9-7: Connections to solder cups (connector type).....	88
Figure 9-8: Methods for securing wires.....	91
Figure 9-9: Connection of solid or stranded wires to PCBs.....	92
Figure 9-10: Connection of coaxial cables to PCBs	93
Figure 10-1: Maximum tilt for assembled PTH component	96
Figure 10-2: Maximum tilt for assembled SMD component.....	96
Figure 10-3: Minimum acceptable wetting on component side.....	102
Figure 10-4: Mounting of rectangular and square end-capped and end-metallized components	104
Figure 10-5: Mounting of cylindrical end-capped components	106
Figure 10-6: Mounting of square end-capped components.....	107
Figure 10-7: Mounting of bottom terminated chip component	108
Figure 10-8: Mounting of components with “L-shape inwards” leads	109
Figure 10-9: Mounting of leadless component with plane termination.....	110
Figure 10-10: Mounting of leaded components with plane termination	111
Figure 10-11: Mounting of leadless castellated ceramic chip carrier components.....	112
Figure 10-12 Mounting of QFN.....	114
Figure 10-13: Mounting of gull-wing leaded components with round, rectangular, ribbon leads	115
Figure 10-14: Mounting of component with “J” leads	116
Figure 10-15: Mounting of components without stress relief	117

Figure 10-16: Mounting of stacked module components with leads protruding vertically from bottom.....	119
Figure 10-17: Typical configuration of ceramic grid array component.....	120
Figure 10-18: High voltage connection	124
Figure 10-19: Solderless assembly configuration	125
Figure 13-1 : Generic soldering verification flow	146
Figure 13-2: Example of soldering log for joints discrepancy log	148
Figure 13-3: Area Array component verification programme flow chart.....	150
Figure 13-4: Assembly verification with electrical testing procedure	154
Figure 13-5: Verification procedure for solderless technology.....	157
Figure 14-1:Vibration test flow chart	167
Figure D-1 : Example of component type preparation and mounting configuration	211
Figure E-1 : Soldered stud terminals	212
Figure E-2 : Soldered turret terminals with single conductors	213
Figure E-3 : Soldered turret terminals with twin conductors	214
Figure E-4 : Soldered bifurcated terminals.....	215
Figure E-5 : Soldered hook terminals	216
Figure E-6 : Soldered cup terminals	217
Figure E-7 : Examples of unacceptable soldered wires	218
Figure E-8 : Hand soldered wire to shielded cable interconnections	219
Figure E-9 : Hand soldered wire to shielded wire interconnections	220
Figure E-10 : Hand soldered wire interconnections - details of defects.....	221
Figure F-1 : Examples of acceptable and not acceptable solder flow through and maximum voids during X-ray	238
Figure F-2 : Angled-transmission X-radiograph showing solder paste shadow due to partial reflow: Reject.....	239
Figure F-3 : Perpendicular transmission X-radiograph showing unacceptable defects	239
Figure F-4 : Perpendicular transmission X-radiograph showing non-wetted footprint.....	240
Figure F-5 : X-radiograph of CGA mounted on PCB showing solder bridge: Reject.....	240
Figure F-6 : X-radiograph of CGA showing solder fillets at base of columns: acceptable....	241

Tables

Table 5-1: Particle concentrations classes 8 till 9 according to ISO 14644-1 (2015).....	34
Table 5-2: EPA requirements summary	36
Table 6-1: Chemical composition of spacecraft solders	51
Table 6-2: Fluxes.....	53
Table 7-1: Clearances for insulation	61
Table 7-2: Solder baths parameters for degolding and pretinning.....	63

Table 8-1: Dimensions and tolerances for clinching component in non-plated hole	76
Table 9-1: Dimensions for connections of solid or stranded wires to PCBs.....	92
Table 9-2: Dimensions for connections of coaxial cables to PCBs.....	93
Table 10-1: Dimensional and solder fillet for rectangular and square end capped components	105
Table 10-2: Dimensional and solder fillet for cylindrical end-capped components.....	106
Table 10-3: Dimensional and solder fillet for square end-capped components	107
Table 10-4: Dimensional and solder fillet for bottom terminated chip components.....	108
Table 10-5: Dimensional and solder fillet for “L-shape inwards” components	109
Table 10-6: Dimensional and solder fillet for leadless component with plane termination ...	110
Table 10-7: Dimensional and solder fillet for leaded components with plane termination....	111
Table 10-8: Dimensional and solder fillet for leadless castellated ceramic chip carrier components	112
Table 10-9: Dimensional and solder fillet for QFN components	114
Table 10-10: Dimensional and solder fillet for gull-wing leaded components with round, rectangular, ribbon leads.....	115
Table 10-11: Dimensional and solder fillet for components with “J” leads.....	116
Table 10-12: Dimensional and solder fillet for components with ribbon terminals without stress relief.....	117
Table 10-13: Dimensional and solder fillet for stacked module components with leads protruding vertically from bottom	119
Table 10-14: Dimensional and solder fillet for area array devices	120
Table 13-1: Conditions invoking verification.....	159
Table 14-1: Modal survey conditions	168
Table 14-2: Minimum severity for sine vibration testing	168
Table 14-3: Minimum severity for random vibration testing.....	169
Table 14-4: Shock sensitive electronic components vs. failure modes (Table reproduced from ECSS-E-HB-32-25A).....	170
Table 14-5: Component microsection location and acceptance criteria	178
Table 14-6: Acceptance criteria for internal defects in ceramic chip capacitors after microsectioning	191