

DIN EN 14777:2005-10 (E)

Space engineering - Multipaction design and test; English version EN 14777:2004

Inhalt

Seite

Foreword	5
Introduction.....	6
1 Scope.....	7
2 Normative references.....	7
3 Terms, definitions and abbreviated terms	8
3.1 Terms and definitions	8
3.2 Abbreviated terms	10
4 Verification	10
4.1 Verification process	10
4.2 Verification levels	11
4.3 Verification plan.....	11
4.3.1 Introduction.....	11
4.3.2 Generation and updating.....	11
4.3.3 Description	11
4.4 Verification routes	12
4.5 Classification of component type.....	12
4.6 Single carrier.....	13
4.6.1 General	13
4.6.2 Margins.....	13
4.6.3 Route to demonstrate conformance.....	14
4.7 Multi-carrier.....	16
4.7.1 General	16
4.7.2 Threshold above equivalent CW peak power	16
4.7.3 Threshold below equivalent CW peak power	16
4.7.4 Route to demonstrate conformance.....	17
5 Design analyses	19
5.1 General	19
5.2 Field analysis	19
5.3 Critical region identification	19
5.4 Multipaction sensitivity analysis	20
5.5 Venting analysis	21
5.6 Inspection.....	21
6 Test conditions	21
6.1 Cleanliness.....	21
6.2 Pressure	21
6.3 Temperature.....	21
6.4 Frequencies	22
6.5 Pulse duration.....	22
6.5.1 General	22
6.5.2 CW units	22
6.5.3 Pulse units	23
6.6 Electron seeding.....	23
6.6.1 CW test	23
6.6.2 Pulsed test	23
6.6.3 Multi-carrier test	23
6.6.4 Seeding sources.....	23
7 Methods of detection	24
7.1 General	24

7.2	Detection methods.....	24
7.3	Detection method parameters.....	24
7.3.1	Sensitivity.....	24
7.3.2	Rise time.....	25
8	Test procedures.....	25
8.1	Test configurations.....	25
8.2	Test facility validation.....	25
8.3	Test execution.....	26
8.3.1	General.....	26
8.3.2	Test procedure.....	26
8.4	Acceptance criteria.....	27
8.4.1	General.....	27
8.4.2	Multi-carrier test.....	27
Annex A (informative)	Multipaction background.....	28
A.1	Physics of multipaction.....	28
A.2	Other physical processes.....	29
A.3	RF operating environment.....	29
A.4	Parallel plate multipaction.....	35
A.5	Coaxial line multipaction.....	40
Annex B (informative)	Component venting.....	43
B.1	Introduction.....	43
B.2	Discharge dependence on pressure.....	43
B.3	Test example.....	43
B.4	Venting dimensions.....	44
B.5	Venting hole calculations.....	44
B.6	Payload vacuum.....	44
B.7	Venting model used.....	44
B.8	Pumping conductance of a venting hole.....	45
B.9	Ultimate pressure.....	46
B.10	Venting experiment.....	48
B.11	Venting guidelines.....	48
Annex C (normative)	Cleaning, handling, storage and contamination.....	50
C.1	Generic processes.....	50
C.2	Cleaning, handling and storage.....	50
C.3	Contaminants.....	52
Annex D (normative)	Electron seeding.....	55
D.1	Introduction.....	55
D.2	CW test.....	55
D.3	Pulsed test.....	55
D.4	Multi-carrier test.....	55
D.5	Types of seeding source.....	57
Annex E (informative)	Test methods.....	58
E.1	Introduction.....	58
E.2	General test methods.....	58
E.3	Transient tests methods.....	62
E.4	Test facility validation.....	69
Bibliography	70

Figures

Figure 1	— Routes to conformance for single carrier.....	15
Figure 2	— Routes to conformance for multi-carrier case.....	18
Figure 3	— The susceptibility zone boundaries for aluminium, copper, silver, gold and alodine 1200.....	20

Figure A.1 — Total secondary electron emission as a function of energy of the incident electron	36
Figure A.2 — Multipaction susceptibility zones for parallel plates of aluminum.....	37
Figure A.3 — Multipaction thresholds for all materials studied, plotted in a single graph as labeled	42
Figure B.1 — The basic venting model	45
Figure E.1 — Generic close to carrier noise multipaction test site	59
Figure E.2 — Principal multipaction test set-up for nulling detection method.....	61
Figure E.3 — Test configuration (mode 1)	63
Figure E.4 — Test configuration (mode 2)	64
Figure E.5 — Detected envelope of a five carrier waveform.....	66
Figure E.6 — Charge probe	68

Tables

Table A.1 — Worst case mode order for susceptible gaps for gold.....	31
Table A.2 — Worst case mode order for susceptible gaps for silver	32
Table A.3 — Worst case mode order for susceptible gaps for aluminium	33
Table A.4 — Worst case mode order for susceptible gaps for alodine.....	34
Table A.5 — Worst case mode order for susceptible gaps for copper	35
Table A.6 — Constants for the most used materials.....	40
Table A.7 — Critical voltages for multipaction in 50 Ω coaxial lines	41
Table B.1 — Outgassing rate for space components used in space applications.....	46