

ISO 12004-1:2008-10 (E)

Metallic materials - Sheet and strip - Determination of forming-limit curves - Part 1: Measurement and application of forming-limit diagrams in the press shop

Contents		Page
Foreword		iv
Introduction		v
1 Scope		1
2 Symbols and abbreviated terms		1
3 Principle		1
4 Test conditions		2
5 Procedure		2
6 Interpretation of results		3
7 Test report		3
Annex A (informative) Modification to forming-limit curves		5
Annex B (informative) Examples of grid patterns currently in use		6
Bibliography		8