

# ISO 4967: 1998-10(E)

## Steel\_- Determination of content of nonmetallic inclusions\_- Micrographic method using standard diagrams

---

<b>Contents</b>		Page
1	Scope .....	1
2	Principle .....	1
3	Sampling .....	3
4	Preparation of specimens .....	5
5	Determination of the content of inclusions .....	6
6	Expression of results .....	8
7	Test report .....	9
 <b>Annex A (normative) ISO Chart diagrams for inclusion groups A, B, C, D and DS .....</b>		<b>10</b>
<b>Annex B (informative) Assessment of a field and of oversized inclusions or stringers .....</b>		<b>25</b>
<b>Annex C (informative) Typical example of results (the total number of fields showing the index, by type of inclusion, for a given number of fields observed) .....</b>		<b>28</b>
<b>Annex D (informative) Relationship between chart diagram indices and inclusion measurements .....</b>		<b>31</b>