

# ISO 148-1:2009-11 (E)

## Metallic materials - Charpy pendulum impact test - Part 1: Test method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>3.1</b>	<b>Energy .....</b>	<b>1</b>
<b>3.2</b>	<b>Test piece .....</b>	<b>2</b>
<b>4</b>	<b>Symbols and abbreviated terms .....</b>	<b>2</b>
<b>5</b>	<b>Principle .....</b>	<b>2</b>
<b>6</b>	<b>Test pieces .....</b>	<b>3</b>
<b>6.1</b>	<b>General .....</b>	<b>3</b>
<b>6.2</b>	<b>Notch geometry .....</b>	<b>3</b>
<b>6.3</b>	<b>Tolerance of the test pieces .....</b>	<b>3</b>
<b>6.4</b>	<b>Preparation of the test pieces .....</b>	<b>3</b>
<b>6.5</b>	<b>Marking of the test pieces .....</b>	<b>3</b>
<b>7</b>	<b>Test equipment .....</b>	<b>4</b>
<b>7.1</b>	<b>General .....</b>	<b>4</b>
<b>7.2</b>	<b>Installation and verification .....</b>	<b>4</b>
<b>7.3</b>	<b>Striker .....</b>	<b>4</b>
<b>8</b>	<b>Test procedure .....</b>	<b>4</b>
<b>8.1</b>	<b>General .....</b>	<b>4</b>
<b>8.2</b>	<b>Test temperature .....</b>	<b>4</b>
<b>8.3</b>	<b>Specimen transfer .....</b>	<b>4</b>
<b>8.4</b>	<b>Exceeding machine capacity .....</b>	<b>5</b>
<b>8.5</b>	<b>Incomplete fracture .....</b>	<b>5</b>
<b>8.6</b>	<b>Test piece jamming .....</b>	<b>5</b>
<b>8.7</b>	<b>Post-fracture inspection .....</b>	<b>5</b>
<b>9</b>	<b>Test report .....</b>	<b>5</b>
<b>9.1</b>	<b>Mandatory information .....</b>	<b>5</b>
<b>9.2</b>	<b>Optional information .....</b>	<b>6</b>
<b>Annex A (informative)</b>	<b>Self-centring tongs .....</b>	<b>9</b>
<b>Annex B (informative)</b>	<b>Lateral expansion .....</b>	<b>11</b>
<b>Annex C (informative)</b>	<b>Fracture appearance .....</b>	<b>14</b>
<b>Annex D (informative)</b>	<b>Absorbed energy vs. temperature and transition temperature .....</b>	<b>17</b>
<b>Annex E (informative)</b>	<b>Measurement uncertainty of an absorbed energy value, KV .....</b>	<b>19</b>
<b>Bibliography .....</b>		<b>26</b>