

# DIN EN ISO 6892-2:2011-05 (E)

## Metallic materials - Tensile testing - Part 2: Method of test at elevated temperature (ISO 6892-2:2011)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1 <b>Scope</b> .....		5
2 <b>Normative references</b> .....		5
3 <b>Terms and definitions</b> .....		5
4 <b>Symbols and designations</b> .....		6
5 <b>Principle</b> .....		7
6 <b>Test piece</b> .....		7
7 <b>Determination of original cross-sectional area (S<sub>0</sub>)</b> .....		7
8 <b>Marking the original gauge length (L<sub>0</sub>)</b> .....		7
9 <b>Apparatus</b> .....		7
10 <b>Test conditions</b> .....		9
11 <b>Determination or calculation of the properties</b> .....		12
12 <b>Test report</b> .....		12
13 <b>Measurement uncertainty</b> .....		13
14 <b>Figures</b> .....		13
15 <b>Annexes</b> .....		14
<b>Annex A (informative) Addition to Annexes B and D of ISO 6892-1:2009</b> .....		<b>15</b>
<b>Annex B (informative) Measurement uncertainty</b> .....		<b>21</b>
<b>Bibliography</b> .....		<b>24</b>