

# ISO 4666-1:2010-10 (E)

## Rubber, vulcanized - Determination of temperature rise and resistance to fatigue in flexometer testing - Part 1: Basic principles

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Test conditions .....</b>	<b>3</b>
<b>5</b>	<b>Test pieces .....</b>	<b>3</b>
<b>5.1</b>	<b>Form and dimensions .....</b>	<b>3</b>
<b>5.2</b>	<b>Preparation .....</b>	<b>3</b>
<b>5.3</b>	<b>Time interval between vulcanization and testing .....</b>	<b>4</b>
<b>5.4</b>	<b>Conditioning .....</b>	<b>4</b>
<b>5.5</b>	<b>Number .....</b>	<b>4</b>
<b>6</b>	<b>Apparatus .....</b>	<b>4</b>
<b>6.1</b>	<b>General .....</b>	<b>4</b>
<b>6.2</b>	<b>Temperature-controlled cabinet .....</b>	<b>4</b>
<b>6.3</b>	<b>Measurement of temperature .....</b>	<b>4</b>
<b>7</b>	<b>Procedure .....</b>	<b>5</b>
<b>7.1</b>	<b>General .....</b>	<b>5</b>
<b>7.2</b>	<b>Temperature of test .....</b>	<b>5</b>
<b>7.3</b>	<b>Measurement of temperature rise .....</b>	<b>5</b>
<b>7.4</b>	<b>Determination of fatigue life .....</b>	<b>5</b>
<b>7.5</b>	<b>Determination of limiting fatigue deformability and limiting fatigue stress .....</b>	<b>5</b>
<b>7.6</b>	<b>Determination of creep .....</b>	<b>6</b>
<b>7.7</b>	<b>Determination of set .....</b>	<b>6</b>
<b>8</b>	<b>Test report .....</b>	<b>6</b>
<b>Annex A (informative) Explanatory notes .....</b>		<b>7</b>
<b>Bibliography .....</b>		<b>9</b>