

ISO 23529:2010-10 (E)

Rubber - General procedures for preparing and conditioning test pieces for physical test methods

Contents		Page
Foreword		iv
1	Scope	1
2	Identification and record keeping	1
3	Standard laboratory conditions	2
3.1	Standard laboratory temperature	2
3.2	Standard laboratory humidity	2
3.3	Other conditions	2
4	Storage of samples and test pieces	2
5	Preparation of test pieces	3
5.1	Test piece thickness	3
5.2	Thickness adjustment	3
5.3	Test piece cutters	5
5.4	Maintenance of cutters	6
5.5	Preparation of test pieces by moulding	6
6	Conditioning	7
6.1	General	7
6.2	Conditioning times for subnormal or elevated temperatures	7
7	Measurement of the dimensions of test pieces	7
7.1	Method A -- For dimensions less than 30 mm	7
7.2	Method B -- For dimensions of 30 mm and up to and including 100 mm	8
7.3	Method C -- For dimensions over 100 mm	8
7.4	Method D -- Non-contact method	8
8	Conditions of test	9
8.1	Duration of test	9
8.2	Temperature and humidity	9
9	Test chambers	10
9.1	General requirements for temperature-controlled chambers	10
9.2	Chambers operating at elevated temperatures	11
9.3	Chambers operating at subnormal temperatures	11
10	Test report	12
Annex A (normative) Conditioning times for rubber test pieces		13
Bibliography		16