

ISO 6892-2:2011-02 (E)

Metallic materials - Tensile testing - Part 2: Method of test at elevated temperature

	Contents	Page
Foreword	iv	
Introduction	v	
1 Scope	1	
2 Normative references	1	
3 Terms and definitions	1	
4 Symbols and designations	2	
5 Principle	3	
6 Test piece	3	
7 Determination of original cross-sectional area (So)	3	
8 Marking the original gauge length (Lo)	3	
9 Apparatus	3	
10 Test conditions	5	
11 Determination or calculation of the properties	8	
12 Test report	8	
13 Measurement uncertainty	9	
14 Figures	9	
15 Annexes	10	
Annex B (informative) Measurement uncertainty	17	
Bibliography	20	