

# DIN EN 12705:2011-08 (E)

## Adhesives for leather and footwear materials - Determination of colour change of white or bright coloured leather surfaces by migration

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Terms and definitions .....	4
4	Principle .....	4
5	Apparatus and materials .....	5
6	Leather .....	5
7	Adhesive .....	5
8	Preparation of test specimens and reference leather pieces .....	5
9	Procedure .....	6
9.1	Colour measurement of test specimens and reference leather pieces .....	6
9.2	Storage/exposure of test specimens and reference leather pieces .....	6
9.2.1	General .....	6
9.2.2	Storage 7 days at (60 ± 2) °C in the dark between glass plates .....	6
9.2.3	Exposure 7 days to light .....	6
9.2.4	Other storage conditions .....	7
10	Expression of results .....	7
11	Test report .....	7