

# DIN EN ISO 7539-6:2012-01 (E)

## Corrosion of metals and alloys - Stress corrosion testing - Part 6: Preparation and use of precracked specimens for tests under constant load or constant displacement (ISO 7539-6:2011)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
1	Scope .....	4
2	Normative references .....	4
3	Terms and definitions .....	5
4	Principle .....	7
5	Specimens .....	8
5.1	General .....	8
5.2	Specimen design .....	9
5.3	Stress intensity factor considerations .....	20
5.4	Specimen preparation .....	25
5.5	Specimen identification .....	26
6	Initiation and propagation of fatigue cracks .....	26
7	Procedure .....	28
7.1	General .....	28
7.2	Environmental considerations .....	28
7.3	Environmental chamber .....	29
7.4	Environmental control and monitoring .....	30
7.5	Determination of KISCC by crack arrest .....	31
7.6	Determination of KISCC by crack initiation .....	34
7.7	Measurement of crack velocity .....	35
8	Test report .....	36
Annex A (normative) Use of notched specimens for stress corrosion tests .....		38
Annex B (normative) Determination of crack growth velocity .....		41