

DIN EN ISO 17636-1:2013-05 (E)

Non-destructive testing of welds - Radiographic testing - Part 1: X- and gamma-ray techniques with film (ISO 17 636-1:2013)

Contents	Page
Foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	6
4 Symbols and abbreviated terms	7
5 Classification of radiographic techniques	7
6 General preparations and requirements	8
6.1 Protection against ionizing radiation	8
6.2 Surface preparation and stage of manufacture	8
6.3 Location of the weld in the radiograph	8
6.4 Identification of radiographs	8
6.5 Marking	8
6.6 Overlap of films	8
6.7 Types and positions of image quality indicators	8
6.8 Evaluation of image quality	9
6.9 Minimum image quality values	9
6.10 Personnel qualification	10
7 Recommended techniques for making radiographs	10
7.1 Test arrangements	10
7.2 Choice of tube voltage and radiation source	16
7.3 Film systems and metal screens	17
7.4 Alignment of beam	19
7.5 Reduction of scattered radiation	19
7.6 Source-to-object distance	19
7.7 Maximum area for a single exposure	22
7.8 Density of radiograph	22
7.9 Processing	22
7.10 Film viewing conditions	23
8 Test report	23
Annex A (normative) Recommended number of exposures which give an acceptable examination of a circumferential butt weld	25
Annex B (normative) Minimum image quality values	30
Bibliography	34